

Bay Cat X Quick Start List

The numbers in parentheses () refer to pages in the Bay Cat X **User Guide**, published 31 May 2005, manual part number 070-0150-00.

Installation

- Installing the DVI Board or SDI Board (6)
- Installing the Bay Cat X Wall Bracket (9)
- Hanging the Bay Cat X on the Wall Bracket (10)
- Connecting Power (12)
- Connecting Picture Sources (14)
- Connecting RS232 Communication (16)

Configuration

- Quick Start (20), to plug it in and go.

For more precise configuration, look at these detailed instructions:

- Setting up a Bay Cat X (22)
- Selecting the Picture (23)
- Adjusting Levels for Digital Computer Sources (26)
- Adjusting Levels for Analog Computer Sources (28)
- Aspect Ratio and Scale Mode (32)
- Adjusting Sharpness (35)
- Position (36)
- Tiling a Display (38)
- Adjusting Color Balance (46)

Cut out and save this card.



clarity
A THOMSON COMPANY

See the back of this card.



Customer Service

email Service@ClarityVisual.com
tech support +1 503 570 4634
tech fax +1 503 570 4657

tech help on web: www.ClarityVisual.com
LOGIN button, then blue LOGIN NOW
Name: tech password: help

Clarity Visual Systems <Superscript>®
27350 SW 95th Avenue, Suite 3038
Wilsonville, OR 97070-7708
main phone +1 503 570 0700
main fax +1 503 682 9441
www.ClarityVisual.com